
Stockbridge Bowl Watershed Survey



Conducted by the BRPC, SBA and Town of Stockbridge June 2012


This project has been financed with Federal Funds from the Environmental Protection Agency (EPA) to the Massachusetts Department of Environmental Protection (DEP) under an s. 319 Nonpoint Source Competitive Grant. The contents do not necessarily reflect the views and policies of EPA or the DEP, nor does the mention of trade names or commercial products constitute endorsement or recommendation for use.

Appendix B

PHOTODOCUMENTATION

Site Conditions along the East Shoreline and Beachwood






















































Mahkeenac Road Survey-

Stormwater drains into Stockbridge Bowl from Rattlesnake Hill, Mahkeenac Heights and Mahkeenac Road. Runoff is channeled away from development enters the lake in a series of drainage ditches.










Typical drainage pipe outlet below the road. This one is just north of Town Beach










Outlet below roadside drainage channel



South of Town
Beach, drainage off
Rattlesnake Hill is
channeled across
the road and
towards the lake





Site Conditions along the West Shoreline















